




TP1



TP2



TP3



D/d-H	D	d	H	G	h	t
10/4,5-8	10	4,5	8	M3	6	3
10/8-10	10	8	10	M4	10	4
15/8,5-15	15	8,5	15	M4	10	4
15/12-15	15	12	15	M4	10	4
20/12-30	20	12	30	M6	18	6
20/14-15	20	14	15	M6	18	6
20/14-19	20	14	19	M4	10	4
20/14-30	20	14	30	M4	10	4
20/16-20	20	16	20	M6	18	6
21/16-22	21	16	22	M6	18	6
25/18-20	25	18	20	M8	23	8
25/20-20	25	20	20	M6	10	6
30/22-20	30	22	20	M8	23	8
30/25-20	30	25	20	M8	23	8
30/18-25	30	18	25	M8	20	6
30/19,5-41	30	19,5	41	M8	20	8
35/25-34	35	25	34	M8	20	8
35/31-15	35	31	15	M8	20	8
40/25-30	40	25	30	M8	23	8
40/33-30	40	33	30	M8	23	8
40/20-50	40	20	50	M8	23	8
40/33-30	40	33	30	M8	23	8
50/35-50	50	35	50	M10	28	10
50/42-30	50	42	30	M10	28	10
50/46-15	50	46	15	M10	28	10
55/44-45	55	44	45	M8	28	8
57/25-44	57	25	44	M10	28	10
57/44-45	57	44	45	M10	28	10
57/25-45	57	25	45	M8	20	8
60/49-60	60	49	60	M10	28	10
70/45-53	70	45	53	M12	28	12
72/64-53	72	64	53	M12	37	12
75/60-40	75	60	40	M12	37	12
95/80-75	95	80	75	M16	41	16
180/148-75	180	148	75	M20	34	20
180/150-75	180	150	75	M20	45	20