



D/d-H	D	d	H
80/20-27	80	20	27
80/20-40	80	20	40
80/21-30	80	21	30
80/21-40	80	21	40
80/22-40	80	22	40
80/25-40	80	25	40
80/25-82	80	25	82
80/27,5-40	80	27,5	40
80/30-35	80	30	35
80/40-30	80	40	30
80/21-100	80	21	100
90/30-45	90	30	45
100/21-40	100	21	40
100/25-40	100	25	40
100/25-70	100	25	70
100/26-40	100	26	40
100/30-35	100	30	35
100/33-40	100	33	40
100/33-75	100	33	75
100/40-70	100	40	70
100/70-40	100	70	40
120/25-40	120	25	40
120/40-40	120	40	40
120/50-40	120	50	40
125/35-125	125	35	125
125/50-125	125	50	125
150/51-100	150	51	100
150/45-180	150	45	180
160/33-160	160	33	160
200/61-100	200	61	100
200/33-200	200	33	200