



KP-D



KP-E



D/H	D	H	G	h
10/10	10	10	M5	12
15/22	15	22	M6	18
20/15	20	15	M6	10
20/24	20	24	M6	18
25/16	25	16	M6	18
25/20	25	20	M6	18
30/30	30	30	M8	20
30/36	30	36	M8	20
35/40	35	40	M8	23
50/50	50	50	M10	28
50/58	50	58	M10	28
50/61	50	61	M8	28
50/67	50	67	M8	33
50/68	50	68	M10	38
60/40	60	40	M10	28
70/58	70	58	M12	32
70/60	70	60	M12	37
75/89	75	89	M12	37
95/80	95	80	M16	41
115/136	115	136	M16	41
118/77	118	77	M16	41

